U. S. DISTRICT COURT FOR THE NORTHERN DISTRICT OF NEW YORK

|--|

DATE: NOVEMBER 8, 2004

PRESIDING JUDGE: HON. FREDERICK J. SCULLIN, JR.

(X) PLAINTIFF () DEFENDANT () COURT

Plaintiff's Will Offer Exhibits:

Exhibit No.	Marked for Identification	Admitted Into Evidence	Remarks	Witness	Exhibit Description
P-1				Quenneville	Niagara Mohawk Video "Boom-Tip Safety"
P-2				Quenneville	NYS Police Photo of poles, marked A and B by witness
P-3				Quenneville	NYS Police Photo of lines, marked C1, C2, D1, D2 and E
P-4				Quenneville	NYS Police Photo of rubber gloves on bucket of truck, "X" marking lip of bucket
P-5				Quenneville	NiMo Photo of boom of truck with pole and wire; marking denoting space (3') between primary lines
P-6				Quenneville	NYS Police Photo of leather gloves
P-7				Quenneville	Altec AN Series Operators, Maintenance and Parts Manual
P-8					Altec AM755-H brochure
P-9					Altec AM600/AM600-H brochure

Exhibits Retu	urned to Counsel (date):_	
Signature: _		

P-10		Altec AM450-AM450-H brochure
P-11		Altec AM550/AM550-H brochure
P-12		Altec AM800/900 specifications
P-13		Altec AN Series specifications
P-14		Altec AL32 brochure
P-15		Altec AA755 brochure
P-16		Altec AA500/600 Series
P-17		Altec brochure showing full line of aerial devices
P-18		Electrical World article dated 07/15/75 concerning Pitman Safety Barrier Kit
P-19		Electric Light & Power article dated August 1975 concerning Pitman Safety Barrier Kit
P-20	Quenneville	Plaintiff's Photo from inspection 8/00, shows bucket and jib and Dr. Durig
P-21	Quenneville	Plaintiff's Photo from inspection 8/00, side view of bucket and jib
P-22	Daino	NiMo Photo of accident scene, back of vehicle and pole (side view), marked with "X" and arrow
P-23		Quotation from J.C. Plastics, Inc. to Altec for Control Handle and Trigger
P-24	Daino	Altec's copy of close-up of top of pole
P-25	Daino	Altec's copy of photo of top of pole
P-26	Daino	OSHA Photo of accident scene, numbered "#13", of ground wire hanging from primary wire
P-27	Mathis	NiMo's Photo of the upper boom, knuckle and bucket, marking of "B", "C" and the jib circled

Exhibits Retu	urned to Counsel (date):_	
	•	
Signature: _		

P-28	Mathis	Plaintiff's Photo from inspection 8/00, side view of vehicle with bucket in air, bucket area circled
P-29	Mathis	Plaintiff's Photo from inspection 8/00, back view of bucket and truck, controls circled
P-30	Mathis	Plaintiff's Photo from inspection 8/00, upper boom, bucket and jib, knuckle near jib is circled
P-31	Mathis	NiMo's Photo of bucket controls, circle and rectangle around controls, marked "A" and "B"
P-32	Mullady	Altec letter to customers dated June 15, 1994, attaching CSN-U-213
P-33	Schremp	Overhead photo of bucket taken at inspection
P-34	Ryan	Overhead photo of bucket taken at inspection
P-35	Schremp	Photo of boom-tip taken at inspection
P-36	Schremp	Niagara Mohawk Video "Safety Stand Down"
P-37	Ryan	Photo of boom-tip
P-38	Nicholson	Photo of entire truck with boom extended
P-39	Nicholson	Photo of boom-tip
P-40	Nicholson	Altec CSN-U-213 – Customer Service Newsletter dated July 12, 1993
P-41	Nicholson	Altec letter to customers dated August 21, 2000, attaching Electrical Continuity Hazard Safety Bulletin
P-42	Sytsma	Close-up photo of bucket control handles
P-43	Chard	Utility Patent Application – Isolation Mechanism for Electrically Isolating Controls of Boomed Apparatus (invented by Joshua T. Chard and Edman R. Blair)
P-44	Chard	NIOSH Safety Study chart

Exhibits Re	turned to Counsel (date):_	
Signature:		

P-45	Chard	Prioritized Decision Criteria List
P-46	Chard	Altec letter to customers re boom tip cover kits
P-47	Chard	Altec document titled "Dielectric Testing for Isolated Controller"
P-48	Chard	Altec drawing no. 716-61925 – Single Handle Controller Assembly, Pilot Pressure System, Green
P-49	Chard	Altec drawing no. 716-61924 – Single Handle Controller Assembly, Full Pressure System, Green
P-50	Chard	Altec Inter-Office Correspondence dated April 10, 2001, from Joshua Chard to VPs, General Managers and Area Managers, re Altec SENTRY Program
P-51	Chard	Altec Marketing Information Letter Number 678: Altec SENTRY Program – Professional Operator Safety Training
P-52	Chard	Altec Marketing Information Letter Number 688: Altec SENTRY Program – Professional Operator Safety Training Services
P-53	Chard	Altec Marketing Information Letter Number 690: Altec SENTRY Program for Non-Insulated Aerial Devices
P-54	Chard	Altec AM650/AM855 Overcenter Material Handler brochure
P-55	Chard	Altec Quotation Number 12345 form for AM650 Aerial Device
P-56		Altec plastic model of insulated aerial lift device (for demonstrative purposes only)

Exhibits Retu	ırned to Counsel (date):	
Signature: _		

P-57	Chard	Danger – Electrical Hazards placards (670-40453 B and 670-40454 B)
P-58	Chard	U.S. Patent and Trademark Office Filing Receipt acknowledging receipt of Patent Application for Isolation mechanism for electrically isolating controls of boomed apparatus
P-59	Chard	Altec Proposal for Project #1065 Start Up (January 28, 1997)
P-60	Chard	Altec memorandum from Mike Anderson to Jim Sytsma dated August 23, 1996 re Plan for Development of Contact Alert
P-61	Chard	Altec document dated 02/20/97 re Agenda for Project #1065 (2-21-97)
P-62	Chard	Contact Alarm Project Critical Issues
P-63	Chard	Three (3) pages of handwritten notes with "1065" at top of first page
P-64	Chard	Hand drawing titled "Project 1065 – Concept Display" dated 5-5-98
P-65	Chard	Letter from Bill Baker to Derald Morgan, Ph.D. dated 09/13/99 re Project #1065: "Continuous Leakage Monitoring System"
P-66	Chard	Altec Proposal dated 09/13/99 for Project 1065
P-67	Chard	Memo from J. Derald Morgan to Bill Baker dated 5/11/00 attaching his final report re his review of Electrical Hazard Warning System for Aerial Devices

Exhibits Ret	turned to Counsel (date):	
Signature:		

P-68	Chard	J. Derald Morgan report titled "Electrical Hazard Warning System for Aerial Devices" (An evaluation of the proposed device as disclosed in Altec's patent application dated July 1, 1998, as a part of the Altec Project #1065, "Continuous Leakage Monitoring System".
P-69	Chard	Document titled "Electrical Hazard Warning System for Aerial Devices" with "Final Draft" handwritten in top right corner
P-70	Chard	United States Patent No. 6,170,607: Electrical Hazard Warning System for Aerial Devices
P-71	Chard	Altec Video, "Insulated Aerial Device Operator's Safety Video"
P-72	Chard	Altec Binder, "Insulated Aerial Devices Self- Directing Training Kit" with CD-ROM
P-73	Chard	<u>Utilities Products Showcase</u> article – "Altec Introduces New Products at 2002 EUFMC" (June 2002)
P-74	Chard	Printout of Altec web page titled "Altec Boom Tip Cover Program"
P-75 to P-175	Sherman	Wes Sherman photographs taken at inspection of accident unit and scene on 07/25/2003
P-176 to P-271	Frost	John Frost photographs taken at inspection of accident unit on 07/25/2003
P-272		Altec Invoice for accident unit
P-273		05/18/2000 memo from Ralph Dudley re "Energized Boom Ends"

Exhibits Re	turned to Couns	sel (date):	
0: 4			
Signature:			

P-274	Accident re-enactment video – May 12, 2000
P-275	Altec Customer Service Notice CSN-A-207 – Boom and Platform Cover Improvement (09/14/2001) – Boom stow cover documents
P-276	New Product Process Objectives
P-277	Altec brochure listing AA, AT, AN, AO, AM and LB Series with general specifications sheet
P-278	Altec LRV Series brochure
P-279	Altec LR III-46 Series brochure
P-280	Altec LBM Series brochure
P-281	Altec L36A/L42A brochure
P-282	Altec AS 300 Series brochure
P-283	Altec A Class brochure
P-284	Altec AO442 brochure
P-285	Altec AO300 brochure
P-286	Altec AM650/AM855 brochure
P-287	Altec Revised Service Bulletin No. SB-AM-203
P-288	Altec Service Bulletin No. SB-AM-203
P-289	Interoffice Correspondence re new electrocution placard "All metal at boom tip"
P-290	Altec letter to operator on dielectric properties
P-291	1993 Customer Service Newsletter "All metal at boom tip connected"
P-292	Chronology of Shaft Protector Kit and related documents on SB-AM-203

Exhibits Returned to Counsel (date):		
Signature:		

P-293		8/25/94 letter to customers re Customer Service Newsletter CSN-U-213 on safety decals and operator manual supplements
P-294		Photograph of single stick control handle with rubber covering over handle (part no. 419734). Note: Component part to single stick control handle assembly no. 419668
P-295		Photographs of single stick control handle, boot cap and trigger disassembled
P-296		Photographs of single stick control handle, boot cap and trigger disassembled
P-297		Memo from Ed Vollmer to Jim Sytsma, Karen Bartlett and Dennis Rasmussen regarding Molded Handle Cost Comparison
P-298		Control handle drawings
P-299		Plastic Handle drawings
P-300	Chard	ISO-Grip Patent Application
P-301	Chard	Dielectric Test Form for Insulated Single Handle Control
P-302		Test Report TR-00117 and Summary – High voltage puncture test on Altec and Terex covers (Dan Bates – 03-27-02)
P-303	Chard	Prioritized Decision Criteria List on covers
P-304		Engineering Change Notice ECN-98-0682
P-305		Engineering Change Notice ECN-00-0707
P-306		Engineering Change Notice ECN-01-0923
P-307		Engineering Change Notice ECN-01-1174

Exhibits Retu	urned to Counsel (date):_	
	•	
Signature: _		

P-308	Altec EN-248-B (origin date 10/07/1986 – revision date 07/10/2001) – Reinforced Fiberglass Cover Specifications
P-309	Photographs referenced in Test Report TR-00117 (Exhibit 167 – Test Report by Dan Bates – High voltage puncture test on Altec and Terex covers)
P-310	Photographs referenced in Vollmer report
P-311	Altec rubber coated control handle with metallic core
P-312	Delrin control handle modeled from Altec rubber coated metallic core handle
P-313	ISO-Grip control assembly
P-314	Vollmer control handle
P-315	Boom tip cover for accident unit
P-316	Death Certificate of Timothy Everts
P-317	Funeral expenses for burial of Timothy Everts
P-318	Income tax returns for years 1995 to 2000
P-319	Union data on benefits
P-320	Table on decedent's earnings history
P-321	Table on decedent's past lost earnings
P-322	Table on decedent's future lost earnings
P-323	Letters of Administration issued to Heidi Everts

Exhibits Returned to Counsel (date):		
· ·		
Signature:		

Plaintiff's May Offer Exhibits:

Exhibit No.	Marked for Identification	Admitted Into Evidence	Remarks	Witness	Exhibit Description
P-324					List of federal court cases with Altec Industries listed as a defendant in a product liability action.
P-325					Expert Witness Report of B. Wesley Sherman, Ph.D.
P-326					CV of B. Wesley Sherman
P-327					Expert Witness Report of John Frost, P.E.
P-328					CV of John Frost, P.E.
P-329					Expert Witness Report of George J. Greene, P.E.
P-330					CV of George J. Greene, P.E.
P-331					Expert Witness Report of Kenneth W. Reagles, Ph.D.
P-332					CV of Kenneth W. Reagles, Ph.D.
P-333					Expert Witness Report of James Sytsma in Walters v. Altec Industries, Inc.
P-334					Photograph of handle developed by Altec for the AA Series
P-335					Altec Stability Test Form – AA Series (with jib)
P-336					Altec Stability Test Form – AA Series with lower boom lifting eye
P-337					Engineering Customer Survey
P-338					Altec Customer Service Newsletter CSN U-218
P-339					Altec Service Tips Bulletin No. ST-AA-221
P-340					Altec Customer Service Newsletter CSN-AA-222

Exhibits Returned to Counsel (date):	
Signature:	

P-341	Altec Customer Service Newsletter CSN-AA-224
_	
P-342	Altec Customer Service Newsletter CSN-AA-226
P-343	Altec Customer Service Newsletter CSN-AA-229
P-344	Altec Customer Service Newsletter CSN-AA-230
P-345	Altec Quality Bodies brochure
P-346	Altec – Exceeding Your Highest Expectations (Goals) brochure
P-347	Altec – Instructions for Upper Control Improvements
P-348	Altec Corporate brochure
P-349	Chance Sentinel Leakage-Current Monitor
P-350	Handwritten notes re current monitoring device
P-351	Evaluation of Proximity Warning Devices – Report prepared by Southwest Research Institute for Bureau of Mines
P-352	A Practical Review of High Voltage Safety Devices for Mobile Cranes
P-353	Documents related to proximity warning devices
P-354	Electroscan Model VIP500 and related documents
P-355	Uprox Proximity Warning Device, printed specs and related materials
P-356	15 Proximity Sensing Q&A's (TURCK)

Exhibits Retu	rned to Counsel (date):	
Signature: _		

	Assorted Patents A. Voltage Responsive Devices and Methods of Voltage Detection B. Proximity Alarm C. Proximity Differential Control
P-357	D. Crane Boom Electrostatic Alarm E. Apparatus for Detecting Power Lines F. Proximity Alarm
	G. Voltage Proximity Detector H. General
P-358	Engineering Release No. 82-073
P-359	Altec's response to Plaintiff's Second Request for Production of Documents #19 – Engineering Change Notice
P-360	Engineering Release No. 86-043
P-361	Altec Interoffice Correspondence
P-362	Documents related to SB-AM-203
P-363	Documents related to SB-AM-203
P-364	Final Assembly Manual for Jib Installation
P-365	Photograph of Altec AA-500 unit 1. Cover over JCAB area 2. Jib
P-366	Photograph of Telelect Trial Mockup 1. Boom tip warning – "Beware – Electrocution Hazard" 2. Boom tip warnings – "Caution" 3. Boom tip warning – "Beware – Operator qualified"

Exhibits Returned to Counsel (date):		
Signature:		

P-367	Photograph of Hi-Ranger A. 1. Alternate bucket shaft cover 2. Jib cylinder mechanism 3. Second half of jib cylinder cover
P-368	Terex-Telelect Operator's Manual
P-369	ANSI A92.2 – 1979 Standard
P-370	Telelect Service Bulletin dated 01/15/1990 – Insulating Properties
P-371	MADDDC Initial Report of Suit
P-372	MADDDC Report of Closed Case
P-373	Terex-Telelect Safety Alert Bulletin SAB001- Electrical Continuity Hazard
P-374	Terex-Telelect Safety Alert Bulletin SAB003 – 2 pages
P-375	Terex-Telelect Product Advisory PA-1003-01 regarding boom tip covers – 2 pages (dated 05/30/2001)
P-376	Terex-Telelect 461104 cover drawings for OM Series – post-manufacture – remedial (dated 05/08/00)
P-377	DHHS (NIOSH) Publication No. 93-105 dated May 1993 – Preventing Injuries and Deaths from Metal-Reinforced Hydraulic Hoses
P-378	Photographs of "DANGER – Electrocution Hazard" warning label
P-379	Engineering Change Notice ECN-97-1147
P-380	Engineering Change Notice ECN-98-0918

Exhibits Returned to Counsel (date):	
Signature:	

P-381		Engineering Change Notice ECN-99-1068
P-382		Altec letter to Customers dated 09/11/2002 – Introduction of new cover kits
P-383		Coroner photographs
P-384		Defendant's responses to Interrogatories in Walters v. Altec Industries, Inc.
P-385		Defendant's responses to Interrogatories in Tymchuk v. Altec Industries, Inc.
P-386	Quenneville	NYS Police Investigation Report
P-387	Quenneville	Plaintiff's Photo from inspection 8/00, knuckle between upper and lower booms circle and jib circled
P-388	Quenneville	Drawing by Matthew Quenneville of accident scene (overhead view)
P-389	Quenneville	Drawing by Matthew Quenneville of accident scene (side view)
P-390	Quenneville	Niagara Mohawk Power Corporation Linemen B Manual – Revised 1967
P-391	Quenneville	Lineman "C" School – Rough Outline of 1 week 1 day
P-392	Quenneville	Outline for Hotstick School
P-393	Quenneville	Timothy Everts' Line Mechanic "C" Hot Stick Training TL 403 – Student Course Record
P-394	Quenneville	Niagara Mohawk's Lesson Plan for Altec AN- 652MH – Generation VI and Altec Manlift Bucket AN-650: Bucket Trucks Training Programs
P-395	Quenneville	Hotstick Manual (No. 586)

Exhibits Ret	turned to Counsel (date):	
Ciamatuma.		
Signature:		

P-396	Quenneville	Niagara Mohawk 15 kv Rubber Glove Training Program
P-397	Quenneville	Timothy Everts' Rubber Glove Committee T & D Training Department –15 kv Gloving Program Checklist
P-398	Quenneville	Drawing by Matthew Quenneville of the angles that the primaries came in to pole (overhead view)
P-399	Quenneville	Copy of Line Hose Training from NiMo's Responses
P-400	Quenneville	NYS Police Photo of knuckle near bucket and jib
P-401	Daino	Drawing by Paul Daino of accident scene (overhead view)
P-402	Daino	NiMo Photo of bucket liner with testing dates
P-403	Daino	NiMo Photo of electric insulation test record
P-404	Daino	Altec's Photo of "Electrocution Hazard" Warning placard near bucket
P-405	Daino	Altec's Photo of accident scene, back of vehicle, transformer on back of truck circled
P-406	Mullady	Niagara Mohawk Attendance Roster for 15 kv Rubber Glove Training Qualified Worker dated 8/31/99
P-407	Ryan	Diagram of top of pole by John Ryan
P-408	Ryan	Diagram of truck and pole by John Ryan
P-409	Nicholson	Photo of boom-tip marked by Stephen Nicholson
P-410	Nicholson	Photo of boom-tip with number 1 through 6 marked on it

Exhibits Ret	turned to Counse	l (date):	
0:			
Signature:			

P-411	Nicholson	Photo of bucket and control handles with areas shaded in red ink
P-412	Chard	7 pages of Operator's Manual, section titled "Operation Near Energized Conductors"
P-413	Tice	Accident Prevention Rules (Orange Book)
P-414	Tice	Accident Prevention Rules – June 1997 (Green Book)
P-415	Chard	Printout of Altec computer screen showing employment status of Joshua T. Chard
P-416	Chard	Altec letter to customers enclosing Altec SENTRY Program brochure
P-417	Chard	Material Handling Capacity Charts dated October 10, 1997: Altec AM650
P-418	Chard	Specifications for a 50 foot hydraulic articulating overcenter aerial device
P-419	Chard	Altec AM650/AM855 Aerial Device Specifications
P-420	Chard	CAD drawing of installed ISO-Grip
P-421	Chard	7 pages from AM50/55 manual
P-422	Chard	Test Report TR-00081a: Evaluation of Insulated Linkages for Pilot Pressure Single Handle Control Assemblies (Bill Baker, 11-29-01)
P-423	Chard	Test Report TR-00081b: Evaluation of Insulated Linkages for Full Pressure Single Handle Control Assemblies (Kelly Williams)
P-424	Chard	Test Log for Project No. A36-80807, Test Report No. TR00081a, starting date 10/25/2001
P-425	Chard	Test Log for Project No. 80827, Test Report No. TR00081b, starting date 11/15/2002

Exhibits Re	turned to Counsel (date):	
Signature:		

	Chard	Test Log for Project No. 80827, Test Report No.
P-426	Onard	TR00081b, starting date 1/4/2002
P-427	Chard	Altec Proposed Research Project RP013 (May 24, 2000) Boom Tip Monitoring System (BTMS)
P-428	Chard	Altec Proposed Research Project RP013 (March 3, 1999) Outline of Development Steps and Projected Timetable
P-429		OSHA investigation file
P-430		State of New York Workers' Compensation Board file on death claim (WCB Case #6000 6499)
P-431		Accident unit inspection video - August 29, 2000
P-432		Engineering drawings on control handle for AA Series, AM Series, AN, AS, Elevators and AT44
P-433		Engineering drawings on plumbing diagram for boom tip with jib
P-434		Engineering drawings on platform mounting assembly with hydraulic extend jib
P-435		Engineering drawings on Placard orientation, AA and AN Series
P-436		Altec dielectric test procedures
P-437		Hi-Ranger – Safety Rules and Precautions – Manual
P-438		Documents related to technical execution of SB-AM-203
P-439		Documents apparently related to SB-AM-203
P-440		Altec digger derrick and Altec aerial device history of product runs

Exhibits Ref	turned to Counsel	(date):	
Signature:			

P-441	Boom Leakage Current Monitor Device/power Line Contact Detector
P-442	Documents re electrical contact alert
P-443	New Product Development – Boom Leakage Current Monitoring Device and Energized Conductor or Grounded Contact Alert
P-444	Documents related to SB-AM-203
P-445	Documents related to SB-AM-203
P-446	07/01/94 letter to customers re Revised Service Bulletin No. SB-AM-203 – Clarification of mandatory action Bulletin SB-AM-203
P-447	Inter-Office Correspondence to Customer Service Newsletter Recipients re CSN-U-214 and CSN-U- 215
P-448	Photographs of Hi-Ranger A. 1. Jib cylinder cover 2. Band of Arrows warnings B. 1. Jib cylinder cover 2. Band of Arrows warnings
P-449	Photographs of Hi-Ranger A. B.

Exhibits Returned to Counsel (date):		
, ,		
Signature:		

P-450	Photographs of Hi-Ranger – Terex-Telelect A. Upper boom in cradle B. Lower and upper boom with jib assembly 1. Lower boom insert 2. Upper boom 3. Jib 4. Winch 5. Jib angle
P-451	Photographs of Terex-Telelect Hi-Ranger A. 3. Jib 4. Winch 5. Jib angle device cover 6. Jib angle device cover 7. Cover under bottom of boom tip 8. Sliding cover over top of jib B. 3. Jib 4. Winch 5. Jib angle device 6. Jib angle device 6. Jib angle device cover 7. Cover under bottom of boom tip 8. Sliding cover over top of jib
P-452	Telelect's Non-Conductive Handle Memo – Schrader to Bassingthwaite (12/30/87)
P-453	Telelect-s Non-Conductive Handle Memo – Shrader to Bassingthwaite (09/22/88)
P-454	1979 Operator's Manual for Pitman Hotstick Articulated Aerial Lift Device

Exhibits Ret	:urned to Counsel (date):	
Signature: _		

P-455	Pitman Safety Barrier Kit A. Cover letter to "Director of Safety" B. Descriptive literature
P-456	Pitman Hotstik Safety Barrier System Background Study
P-457	ANSI A92.2 – 1990 Standard
P-458	ANSI Z535.4 – 1991 Standard
P-459	Photographs of Pitman Safety Barrier Kit in use on bucket truck
P-460	Photographs of Pitman Safety Barrier Kit in use on bucket truck
P-461	Photographs of Pitman Safety Barrier Kit in use on bucket truck
P-462	Terex-Telelect Campaign Bulletin 04-543-01 – Danger decal, Controls are not insulated or isolated
P-463	Altec drawing – Cover, Jib Winch (08/14/92)
P-464	Altec drawing – Cover, Jib Winch Extension (10/22/92)
P-465	Altec drawing – Cover, Controller (11/14/92)
P-466	Altec drawing – Cover, Platform Cam (09/16/93)
P-467	Altec drawing – Cover, Bucket Dump Rotator (09/10/93)
P-468	Altec drawing – Cover, Boom Tip, AM, with Hydr. Extend Jib (07/27/93)
P-469	Altec drawing – Cover, Jib Extension Cylinder (03/02/93)

Exhibits Returned to C	counsel (date):
	,
Signature:	

P-470	Quotation from J. C. Plastics, Inc. to Karen Bartlett with Altec dated 09/07/200 re Control Handle and Trigger
P-471	Test Report TR-00060 and Test Summary – Molded Plastic Control Handle Structural Test (Ed Vollmer – 04/04/01)
P-472	Test Report TR-00071 – Molded Plastic Control Handle Operational Endurance Test
P-473	Engineering drawing of ISO-Grip illustrating assembly and listing of component parts (01/29/2002)
P-474	Engineering drawing of assembled ISO-Grip with component parts description reference index guide (01/20/2002)
P-475	Test Log – Isolated Controller Cycle Testing (10/25/2001)
P-476	Test Log – Isolated control handle, test 2, full pressure controls (01/04/2002)
P-477	Price and feature quotation for AM 50 & 55 with ISO-Grip (p. 3 references Altec ISO-Grip insulated single handle control – rated 26.5kV
P-478	Altec drawing No. 703-91080 – Cover Assembly, Boom Tip, Material Handling (10/04/99)
P-479	Instructions – Cover Improvement Installation (Kit Part Nos. 750-40367 and 750-40396)
P-480	Instructions – Cover Improvement Installation (Kit Part Nos. 750-40373, 750-40398, 750-40403, 750-40404, 750-40405, and 750-40406)

Exhibits Returned to Counsel (date):	
Signature:	

P-481	Instructions – Cover Improvement Installation (Kit Part Nos. 750-40382, 750-40397, 750-40399, 750-40400, 750-40401, and 750-40402)
P-482	Instructions (draft) – Cover Improvement Installation (Kit Part Nos. 750-40384 and 750-40394)
P-483	Instructions – Cover Improvement Installation (Kit Part No. 750-40385 and 750-40395)
P-484	Instructions – Cover Improvement Installation (Kit Part No. 750-40385)
P-485	Instructions – Cover Improvement Installation (Kit Part No. 750-40389)
P-486	(A-P) Photographs of Georgia Power unit taken by Joe Lane in Atlanta on 10/27/2002
P-487	Altec engineering drawing no. 706-60094 (Section B-B) – Cover, Jib Winch Extension
P-488	Altec engineering drawing no. 706-60094 (Section F-F) – Cover, Jib Winch Extension
P-489	Photographs of <u>Slaughter</u> inspection taken by Joe Lane on 12/11/2002.
P-490	Danger label – "DANGER – Electrocution Hazard" (label #670-40252 D)
P-491	Telelect plastic D-ring control handle
P-492	Telelect old-style plastic coated main control
P-493	Exemplar boom tip cover #1
P-494	Exemplar boom tip cover #2
P-495	Dr. Ken Reagles' report on pecuniary losses

Exhibits Re	turned to Counsel (date):	
	, ,	
Signature:		

Page 23 of 23

P-496 to P-506		Family photographs of Tim, Heidi and Tiffany Everts
P-507		Rubber gloves
P-508		Rubber line hoses
P-509		Complaint filed in this action
P-510		All discovery responses in this action

Exhibits Returned to Counsel (date):	
, ,	
Signature:	